

<b>Release Date</b>	<b>Version History</b>	<b>Software Update Tools</b>
19-Nov-2019	<p>Wi-Fi v3.0.0, MCU v4.1.0</p> <ul style="list-style-type: none"> <li>Fixed subwoofer volume issue</li> <li>Fixed IR control issue on speaker volume</li> <li>Wi-Fi always accessible from all sources</li> <li>Support wake-up speaker by KEF Control app, Spotify Connect and DLNA (only applicable for speaker serial number after LS50W13074K24L/R2G)</li> <li>Various improvement and bug fixes</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V4.0.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V4.0.0</li> </ul>
15-Oct-18	<p>Wi-Fi v2.1.0</p> <ul style="list-style-type: none"> <li>Add gapless support for KEF Stream App</li> <li>Fixed TIDAL unsupported format for some cases</li> </ul> <p>MCU v3.0.0, DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V4.0.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V4.0.0</li> </ul>
27-Jun-18	<p>MCU v3.0.0 , Wi-Fi v2.0.0</p> <ul style="list-style-type: none"> <li>Add TCP/IP control for 3rd party developers</li> <li>Fixed EQ access issue for certain Android devices</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V3.0.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V3.0.0</li> </ul>
16-April-18	<p>MCU v2.5.0</p> <ul style="list-style-type: none"> <li>Extended support for programmable IR remote controls (Compatibility refer to FAQ section A12)</li> </ul> <p>Wi-Fi v1.2.0</p> <ul style="list-style-type: none"> <li>Add “QPlay” support for China</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V3.0.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V3.0.0</li> </ul>

15-Nov-17	<p>MCU v2.4.0</p> <ul style="list-style-type: none"> <li>Fixed low voltage protection issue causing system or slave error</li> </ul> <p>Wi-Fi v1.1.6</p> <ul style="list-style-type: none"> <li>Improved Roon support</li> <li>Various bug fixes that improve app stability</li> <li>Bug fixes to improve firmware upgrade stability</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V2.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V2.0</li> </ul>
9-Oct-17	<p>MCU v2.3.0</p> <ul style="list-style-type: none"> <li>Add support to swap between Left and Right speakers</li> </ul> <p>Wi-Fi v1.1.4</p> <ul style="list-style-type: none"> <li>Add “Spotify Connect” support (compatibility varies by country)</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V1.3</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V1.1.0.0</li> </ul>
22-May-17	<p>MCU v2.2.1</p> <ul style="list-style-type: none"> <li>Fixed Wi-Fi network memory occasionally lost after system restarting</li> <li>Fixed potential left speaker no output issue</li> <li>Each source has now individual volume memory</li> <li>Add the ability to disable Auto-Standby time</li> <li>Other bug fixes and improvements</li> </ul> <p>Wi-Fi v1.1.3</p> <ul style="list-style-type: none"> <li>Add ALAC format support</li> <li>Fixed volume control over App issue</li> <li>Other bug fixes and improvements</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>LS50_Wireless_Firmware_Update_Tool_V1.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>LS50W_FW_Upgrade_Tool_V1.1.0.0</li> </ul>