

Release Note

Speaker Firmware

24-Nov-2020	<p>Version 1.2</p> <ul style="list-style-type: none">• Fixed Wi-Fi LED incorrect status• Fix loud subwoofer volume when playing power on feedback tone• Fix volume jump when user plugs in secondary speaker while primary speaker is playing• Reduced feedback tone volume• Improved firmware update status reporting• Improved speaker system stability• Various music streaming services playback improvements and bug fixes• Various Wi-Fi improvements• Various improvements and bug fixes• Increase additional logging for volume and TV issues
07-Oct-2020	<p>Version 1.1</p> <p>Many improvements and bug fixes</p> <ul style="list-style-type: none">• Second source wake up is now supported (needs to be enabled via KEF Connect 1.1)• Final feedback tones have been implemented• Improved DSP• Improved system logging
22-Sept-2020	<p>Version 1.0</p>

KEF Connect APP

24-Nov-2020	iOS Version 1.3.1 Android Version 1.3.1 <ul style="list-style-type: none"> • Allow for disabling the share of usage data with Google from KEF Connect • Various improvements, bug and crash fixes
9-Nov-2020	iOS Version 1.3.0 <ul style="list-style-type: none"> • Media Server support • Various improvements, bug and crash fixes Android Version 1.3.0 <ul style="list-style-type: none"> • Various improvements, bug and crash fixes
22-Oct-2020	iOS Version 1.2.1 Android Version 1.2.1 <ul style="list-style-type: none"> • Various improvements, bug and crash fixes
12-Oct-2020	iOS Version 1.2 Android Version 1.2 <ul style="list-style-type: none"> • Fixed and improved incorrect firmware update status • Added subscribe newsletter button in Profile screen • Added Standby info on home screen • Added alert for disabled/unavailable items in music services • Updated second wake-up source display • Various GUI improvements • Various improvements, bug and crash fixes
07-Oct-2020	iOS Version 1.1 Android Version 1.1 <ul style="list-style-type: none"> • iOS14 support • Fixed issue on putting speaker into Standby using the Source buttons in remote control section • New Standby modes ECO/30/60/none • Second source wake up now supported (not supported in ECO mode, only work with firmware version 1.1 or later) • Updated user authentication method, users who created account in earlier app version or developer build will need to create new account again • Updated MQA indicators (now correctly reflect MQA, MQA Studio, and MQA core)
22-Sept-2020	iOS Version 1.0 Android Version 1.0